

Download File PDF Honda Check Engine Code

#Jenny



Finally I get this ebook, thanks for all these I can get now!

#Rio



Cool! I'am really happy

#Markus Jensen



I did not think that this would work, my best friend showed me this website, and it does! I get my most wanted eBook

#Hun Tsu



wtf this great ebook for free?!

#Che Salsa



My friends are so mad that they do not know how I have all the high quality ebook which they do not!

#Diego Butler



so many fake sites. this is the first one which worked! Many thanks

PGM-FI System

Crankshaft Position/Top Dead Center/Cylinder Position (CKP/TDC/CYP) Sensor

P0335 The scan tool indicates Diagnostic Trouble Code (DTC) P0335. A malfunction in the Crankshaft Position (CKP) sensor circuit.

P0336 The scan tool indicates Diagnostic Trouble Code (DTC) P0336. A range/performance problem in the Crankshaft Position (CKP) sensor circuit.

P1361 The scan tool indicates Diagnostic Trouble Code (DTC) P1361. Intermittent interruption in the Top Dead Center (TDC) sensor circuit.

P1362 The scan tool indicates Diagnostic Trouble Code (DTC) P1362. No signal in the Top Dead Center (TDC) sensor circuit.

P1381 The scan tool indicates Diagnostic Trouble Code (DTC) P1381. Intermittent interruption in the Cylinder Position (CYP) sensor circuit.

P1382 The scan tool indicates Diagnostic Trouble Code (DTC) P1382. No signal in the Cylinder Position (CYP) sensor circuit.

Description
The CKP sensor determines timing for fuel injection and ignition of each cylinder and also detects engine speed. The TDC sensor determines ignition timing at start-up (cranking) and when crank angle is abnormal. The CYP sensor detects the position of No. 1 cylinder for sequential fuel injection to each cylinder. The CKP/TDC/CYP Sensor is built into the distributor.

NOTE: If DTC P1382 is stored at the same time as DTC P0335, P0336, P1361, P1362, P1381 and/or P1382, troubleshoot DTC P1382 first, then troubleshoot these DTCs.

DIAGNOSTIC AID

Problem verification

1. Do the CKP/TDC sensor tests.
2. Start the engine.

Is DTC P0335, P0336, P1361, P1362, P1381 and/or P1382 cleared?

YES

Check for air leaks in the CKP/TDC sensor.

1. Turn the ignition switch OFF.
2. Disconnect the distributor cap connection.
3. Measure the resistance between the terminals of the individual sensor "Cam" coils.

NO

Replace the distributor cap/rotor. Recheck the distributor cap.

YES

(E) page 11-110

SENSOR	WIRING	CONNECTOR	TERMINAL	WIRING
CKP	P0335	1	CR	BLK
CKP	P0336	2	CR	WHI
TDC	P1361	1	CR	GRN
TDC	P1362	2	CR	RED
CYP	P1381	1	CR	GRN
CYP	P1382	2	CR	BLK

[Download PDF version of :
Honda Check Engine Code](#)