

Download File PDF Repair Manual 2 7 Liter V6 5v Fuel Injection Ignition Engine Code S Bas Group 24

#Jenny



Finally I get this ebook, thanks for all these I can get now!

#Rio



Cool! I'am really happy

#Markus Jensen



I did not think that this would work, my best friend showed me this website, and it does! I get my most wanted eBook

#Hun Tsu



wtf this great ebook for free?!

#Che Salsa



My friends are so mad that they do not know how I have all the high quality ebook which they do not!

#Diego Butler



so many fake sites. this is the first one which worked! Many thanks

Secondary air system

Page 10 of 24

2640

Installation location => Installation locations Overview

=> Repair Manual: 2.7 Liter V6 5V (Turbo Fuel Injection & Ignition, Engine Codes): APB, Repair Group 24

Test requirement:

- Output Diagnostic Test Mode (DTM) performed

Checking internal resistance

- Disconnect harness connector from Secondary Air Injection (AIR) valve A112.
- Connect multimeter at valve for resistance measurement.
 - Specified value: 25 ... 35 Ω
 - If specified value is not obtained, replace Secondary Air Injection (AIR) solenoid valve A112.



[Download PDF version of :](#)
Repair Manual 2 7 Liter V6 5v Fuel Injection Ignition Engine Code S Bas Group 24

http://127.0.0.1:8080/uedi/View/Display/Action/Content/repairManual/ALDEKBA/2640_2642

carmanualsonline.info