

Download File PDF Ricoh Aficio Mp 2500 Service Manual

#Jenny



Finally I get this ebook, thanks for all these I can get now!

#Rio



Cool! I'am really happy

#Markus Jensen



I did not think that this would work, my best friend showed me this website, and it does! I get my most wanted eBook

#Hun Tsu



wtf this great ebook for free?!

#Che Salsa



My friends are so mad that they do not know how I have all the high quality ebook which they do not!

#Diego Butler



so many fake sites. this is the first one which worked! Many thanks

CÓPIA NÃO CONTROLADA

Service Call Conditions

4.1.2 SC CODE DESCRIPTIONS

No. Definition	Symptom	Possible Cause
101	Exposure Lamp Error The peak white level is (4255 digit or less (8 bit) when scanning the white plate.	<ul style="list-style-type: none">Exposure lamp defectiveExposure lamp stabilizer defectiveExposure lamp connector defectiveDirty scanner motor or scanner error out of positionSBU board defectiveSBU connector defectiveLens block out of positionIncorrect position or width of white plate scanning (SP4015)
120	Scanner home position error 1 The scanner home position sensor does not detect the off condition during initialization or copying.	<ul style="list-style-type: none">Scanner home position sensor defectiveScanner drive motor defectiveScanner home position sensor connector defectiveScanner drive motor connector defectiveBICU board defective
121	Scanner home position error 2 The scanner home position sensor does not detect the on condition during initialization or copying.	<ul style="list-style-type: none">Scanner home position sensor defectiveScanner drive motor defectiveScanner home position sensor connector defectiveScanner drive motor connector

0010

CÓPIA NÃO CONTROLADA

SM

[Download PDF version of :](#)
Ricoh Aficio Mp 2500 Service Manual